



Magnetech
INDUSTRIAL SERVICES, INC.

We provide solutions

Field Generator Repair


Client Type: Electric Utility

Equipment Involved: ABB 13,000 VAC, 514 RPM Generator

Challenge: Generator was operated beyond rated capacity causing damage to threads in laminated pole core.

Solution: As ABB authorized service provider, travel to customer site and install new ABB pole cores per OEM specification.

Project Scope: Remove rotor and poles; install new poles and connect, test and insulate as needed; install rotor. Balance rotor. Align.



Magnetech Industrial Services

800 Nave Road SE
Massillon, OH 44646
Phone: 330-830-3500
Fax: 330-830-3520
E-mail: info@magnetech.com